


Anquellung und Hochziehen tieferliegender Schichten durch nachfolgende Lackschichten beim Lackiervorgang oder bei der Trocknung.



--



20fache Vergrößerung

URSACHEN

- 1| Zu lange Zwischenablüftzeiten bei Nass-in-Nass-Arbeiten mit 2K-Produkten (Gelierzphase).
- 2| Überlackieren lösemittlempfindlicher Schichten (NC-/TPA) mit falschen Reparatursystemen oder zu dicken Schichten.
- 3| Isolierschichten nicht dick genug (zu dünn gespritzt bzw. zu weit abgeschliffen).
- 4| Untergrund nicht durchgetrocknet.

VERMEIDUNG

- 1| Empfohlene Zwischenablüftzeiten einhalten.
- 2| Lösemitteltest durchführen und geeigneten Aufbau wählen.

3| Empfohlene Schichtdicken einhalten.

4| Untergrund ggf. nachtrocknen (z. B. mit IR).

REPARATUR

Den Lackaufbau bis auf „gesunde“ Schichten abschleifen. Neuaufbau mit geeigneten Grund- und Decklackmaterialien.

DISCLAIMER

The data contained in this publication are based on our current knowledge and experience. In view of the many factors that may affect processing and application of our products, these data do not relieve processors from carrying out their own investigations and tests; neither do these data imply any guarantee of certain properties, nor the suitability of the products for a specific purpose. Any descriptions, drawings, photographs, data, proportions, weights etc. given herein are for general information purpose only; they may change without prior information and do not constitute the agreed contractual quality of the products (product specification). The latest version supersedes all previous versions. You can obtain the latest version from our website at www.rmpaint.com or directly from your sales partner. It is the responsibility of the recipient of our products to ensure that any proprietary rights and existing laws and legislation are observed.