

Ringförmige, meist helle, weißliche Flecken/Anquellungen auf der Lackoberfläche durch Eintrocknen von Wasser, in Verbindung mit Kalk und Salz. Die Innenflächen sind meistens unversehrt, die Randzonen markieren sich durch leichte Erhebungen.

URSACHEN

- 1| Nicht ausreichende Trocknung frischer Lackierungen.
- 2| Zu hohe Schichtdicken sind besonders empfindlich.
- 3| Falsche Härterdosierung.

VERMEIDUNG

Empfohlene Trocknung sowie Schichtdicken und Mischungsverhältnisse einhalten.

REPARATUR

Als ersten Schritt mit sauberem Wasser abwaschen; falls so nicht zu entfernen, mit einer Feinpolierpaste aufpolieren und mit einem handelsüblichen Hochglanzpolitur nachpolieren. Größere Störungen anschleifen und neu lackieren.

DISCLAIMER

The data contained in this publication are based on our current knowledge and experience. In view of the many factors that may affect processing and application of our products, these data do not relieve processors from carrying out their own investigations and tests; neither do these data imply any guarantee of certain properties, nor the suitability of the products for a specific purpose. Any descriptions, drawings, photographs, data, proportions, weights etc. given herein are for general information purpose only; they may change without prior information and do not constitute the agreed contractual quality of the products (product specification). The latest version supersedes all previous versions. You can obtain the latest version from our website at www.rmpaint.com or directly from your sales partner. It is the responsibility of the recipient of our products to ensure that any proprietary rights and existing laws and legislation are observed.